

Recovery from “The Great East Japan Earthquake”

(Update 5, April 8)

The recovery status from the Great East Japan Earthquake at Sanken's production sites are as follows.

Due to the large aftershock occurred at 11:32 pm on Thursday April 7 and the resulting power outage, production at Yamagata Sanken Co., Ltd. (Higashine, Yamagata Prefecture), which had been partially resumed, is suspended. The projected recovery of the production lines will be announced when and as appropriate.

Fukushima Sanken Co., Ltd. (Nihonmatsu, Fukushima Prefecture) and Kashima Sanken Co., Ltd. (Kamisu, Ibaraki Prefecture) are operating as normal.

At present, Sanken and all of its affiliates are making every effort to resume and increase supply of our products to our customers. We regret, however, to inform that due to troubles in logistics infrastructure and unpredictable schedule of rolling black-outs, our latest estimate tells that it takes some time before we regain our stable, full production and shipment of our products.

Inquiries to:
IR office
Sanken Electric Co., Ltd.